



# IECEx Quality Assessment Report Summary

## INTERNATIONAL ELECTROTECHNICAL COMMISSION IEC Certification System for Explosive Atmospheres

for rules and details of the IECEx Scheme visit [www.iecex.com](http://www.iecex.com)

|   |   |   |
|---|---|---|
| QAR Ref. No.:                               | <b>DE/TUN/QAR13.0008/13</b>   | Page 1 of 2   |
| QAR Free Ref. No.:                          | <b>25 216 393452</b>  | Status: <b>Issued</b>   |
| Details of change:                          | <ul style="list-style-type: none"><li>- Re-Assessment</li><li>- Change in the audited locations (the location in Überlingen and Hamburg are be no longer relevant)</li><li>- Change in the named type of protection (type of protection "m" and "p" are be no longer relevant)</li></ul>  | Date of issue: <b>2025-11-12</b><br>Valid until: <b>2028-09-06</b><br>Audit date: <b>2025-03-19</b> |
| Location(s) audited:                        | <b>SICK AG</b><br>Gisela-Sick-Straße 1<br>79276 Reute<br><b>Germany</b><br><br><b>SICK AG</b><br>Erwin-Sick-Str. 1<br>79183 Waldkirch<br><b>Germany</b><br><br><b>SICK Kft</b><br>Fő út 49<br>9184 Kunsziget<br><b>Hungary</b><br><br><b>SICK AG</b><br>Abbruchstraße 4<br>with additional location Weißerlenstrasse 8<br>76108 Freiburg<br><b>Germany</b>  |   |
| Issuing ExCB:                               | <b>TUN - TÜV NORD CERT GmbH</b>   |   |
| Manufacturer:                               | <b>SICK AG</b><br>Erwin-Sick-Straße 1<br>79183 Waldkirch  |   |
| Location of Manufacturer:                   | <b>Germany</b>  |   |
| Product information:                        | Apparatus and equipment for measurement and control   |   |
| Type of protection:                         | <b>Flameproof enclosures "d" Increased safety "e" Intrinsic safety "i" Type of protection "n" Optical radiation "op is" Dust protection by enclosures "t"</b>   |   |
| Related QARs:                               | <div>DE/TUN/QAR13.0008/00</div> <div>DE/TUN/QAR13.0008/03</div> <div>DE/TUN/QAR13.0008/06</div> <div>DE/TUN/QAR13.0008/09</div> <div>DE/TUN/QAR13.0008/12</div> <div>DE/TUN/QAR13.0008/01</div> <div>DE/TUN/QAR13.0008/04</div> <div>DE/TUN/QAR13.0008/07</div> <div>DE/TUN/QAR13.0008/10</div> <div>DE/TUN/QAR13.0008/02</div> <div>DE/TUN/QAR13.0008/05</div> <div>DE/TUN/QAR13.0008/08</div> <div>DE/TUN/QAR13.0008/11</div> |   |
| Related Certificates (manual insertion)::   |   |   |
| Related Certificates (automatic linking)::  |   |   |
| Related Certificates for previous versions: |   |   |
| IECEx BVS 13.0111X issue: 0                 | IECEx BVS 13.0111X issue: 1   | IECEx BVS 13.0111X issue: 2   |
| -- Continued on the next page               |   |   |



# IECEx Quality Assessment Report Summary

QAR Ref. No.: **DE/TUN/QAR13.0008/13**

Page 2 of 2

Related Certificates for  
previous versions (continued):

|                              |                              |                              |
|------------------------------|------------------------------|------------------------------|
| IECEx BVS 13.0111X issue: 3  | IECEx BVS 17.0032X issue: 0  | IECEx BVS 17.0032X issue: 1  |
| IECEx BVS 17.0059X issue: 1  | IECEx BVS 17.0059X issue: 2  | IECEx BVS 17.0060U issue: 1  |
| IECEx BVS 19.0004X issue: 0  | IECEx BVS 19.0004X issue: 1  | IECEx BVS 19.0005X issue: 0  |
| IECEx BVS 19.0005X issue: 1  | IECEx BVS 19.0006X issue: 0  | IECEx BVS 19.0006X issue: 1  |
| IECEx EPS 11.0006X issue: 3  | IECEx EPS 15.0016X issue: 0  | IECEx EPS 15.0016X issue: 1  |
| IECEx IBE 14.0024X issue: 0  | IECEx IBE 14.0024X issue: 1  | IECEx IBE 14.0025X issue: 0  |
| IECEx IBE 14.0025X issue: 1  | IECEx KIWA 20.0014X issue: 0 | IECEx KIWA 20.0015X issue: 0 |
| IECEx KIWA 20.0016X issue: 0 | IECEx PTB 14.0030 issue: 0   | IECEx PTB 14.0030 issue: 1   |
| IECEx PTB 14.0030 issue: 2   | IECEx PTB 14.0031 issue: 0   | IECEx PTB 14.0031 issue: 1   |
| IECEx PTB 14.0031 issue: 2   | IECEx TUN 14.0038 issue: 0   | IECEx TUN 14.0038 issue: 1   |
| IECEx TUN 14.0038 issue: 2   | IECEx TUR 18.0067X issue: 0  | IECEx TUR 18.0067X issue: 1  |
| IECEx TUR 18.0067X issue: 2  | IECEx TUR 20.0064X issue: 0  | IECEx ULD 23.0037X issue: 0  |
| IECEx ULD 23.0037X issue: 1  |                              |                              |

Comments: The company is also certified acc. ISO 9001 and Directive 2014/34/EU-Annex IV